

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>No chg.</i>	LOCATION <i>1045-40th St</i>
DATE <i>10-3-32</i>	PURPOSE <i>Repair on porch of dwelling</i>
ZONE	OWNER <i>G. P. Willis</i>
	ARCH'T
	CONT-R <i>Owner</i>

VAL <i>25⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
-------------------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK--REMARKS
	<p data-bbox="365 813 519 859">COMPLETE AND O. K.</p> <p data-bbox="1161 833 1323 859">INSPECTOR</p>