

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. B 3922	LOCATION 1712 - 93 rd St			
DATE 7/5/40	PURPOSE Remodel of basement apart			
ZONE —	OWNER H. Buck Davis			
	ARCH'T. —			
	CONTR. Owner			
VAL. 1000 ←	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
2-16-40	2 ⁵ ' Larp Frame on Quarters
	COMPLETE AND O. K. INSPECTOR