

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-9845</i>	LOCATION <i>187-40th Way.</i>
DATE <i>1/21/42</i>	PURPOSE <i>Erect new dwell'g for</i>
ZONE	OWNER <i>J. E. Roland &</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>4000⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
-------------------------------	---------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area 1011^{sq} @ <u>350</u></i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS	
1/28-	1 st	Deep Furrows at Point
3/6	2 "	Furrows at Point
3/25-	3 "	Lath Joints at Point
4/15-	4 "	Lath Joints at Point

COMPLETE
AND O. K.

INSPECTOR