

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## ADDITIONAL PERMIT TYPE BUILDINGS

PERMIT NO. <i>A-1593</i>	LOCATION <i>3040 - 11 St</i>			
DATE <i>4/27/53</i>	PURPOSE <i>To make addition to building</i>			
ZONE <i>Gen Com</i>	OWNER <i>permit # 1384 - A. J. Morrison</i>			
ARCH'T	CONT'R <i>Owner</i>			
VAL. <i>3000<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
6/11/34	All work done under this Additional Permit Completed O.K.
	A.W. Campbell
6/11/34	COMPLETE AND O.K. <i>A.W. Campbell</i> INSPECTOR