

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>4-7650</i>	LOCATION <i>1501 - 16<sup>th</sup> Street</i>			
DATE <i>1/3/38</i>	PURPOSE <i>Repairs to fire loss</i>			
ZONE	OWNER <i>Maud M. Gilpin</i>			
	ARCH'T.			
	CONTR. <i>Frank Maloney</i>			
VAL. <i>400<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
			<i>5</i>	
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE

CONDITION OF WORK-REMARKS

4/5/38

2<sup>nd</sup> ASP - Frame for Rib areas to rear part of upper  
floor and roof damaged by fire  
A. H. Campbell

COMPLETE  
AND O. K.

INSPECTOR