

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-6364</i>	LOCATION <i>1873-52nd St.</i>
DATE <i>5/24/37</i>	PURPOSE <i>Erect new dwlg year-</i>
ZONE <i>1-Fam-</i>	OWNER <i>J. L. Wahl</i>
	ARCH'T. <i>Copper Roof Co. 216-21st St</i>
	CONT'R. <i>Copper Roof Co. 216-21st St</i>

VAL. <i>3750⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
-------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFIS	<i>Area 925^{sq} ft</i>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
5/28-37	1 st Insp Frame OK Printer
7/7-37	2 nd Insp Frame OK Printer
7/20-37	3 Insp Lock " Printer

COMPLETE
AND O. K.

INSPECTOR