

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD.

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>5394</i>	LOCATION <i>1120 J</i>
DATE <i>1/19/29</i>	PURPOSE <i>Resurf. 10 ft concrete Asbestos</i>
ZONE	OWNER <i>Union Garage</i>
	ARCHT
	CONTR <i>San Joaquin lumber</i>

VAL. <i>1200</i>	STORIES	ROOMS	APTS.	SIZE
---------------------	---------	-------	-------	------

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand-pipes			

DATE

CONDITION OF WORK—REMARKS

**COMPLETED
AND O. K.**

INSPECTOR