

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-5376</i>	LOCATION <i>1010 - H - Street</i>
DATE <i>12/11/36</i>	PURPOSE <i>Re roof dwlg. complete</i>
ZONE	OWNER <i>Becker</i>
	ARCH'T.
	CONT'R. <i>Roof Sew. Co.</i>

VAL. <i>1600⁰⁰</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
-------------------------------	------------------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
	<p data-bbox="336 975 487 1023">COMPLETE AND O. K.</p> <p data-bbox="1310 999 1470 1023">INSPECTOR</p>