

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <b>7539</b>	LOCATION <b>1616 S In</b>
	PURPOSE <b>Remodel of Show Room Office</b>
DATE <b>1/13/31</b>	OWNER <b>Wm Coffey</b>
ZONE <b>G-1 Com</b>	ARCH'T <b>J. Campbell</b>
	CONT'R <b>J. Campbell Contractor Co</b>

PHONES

VAL. <b>3000 -</b>	STORIES	ROOMS	APTS.	SIZE
--------------------	---------	-------	-------	------

Steel Tested by	<b>1-Story Mechanical Floor for Office Auto Show Room</b>	Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfcd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand Pipes			

DATE	CONDITION OF WORK—REMARKS
1/9/31	Preliminary Insps of Alterations & Retain In Auto Sales Bldg. New Bldg. Masonite Office on 1st and 2nd floors. A.H. Campbell
1/15/31	2 <sup>ND</sup> INSP (PARTIAL) FLOOR A.H. Campbell
1/19/31	2 <sup>ND</sup> INSP (BALANCE) " OK A.H. Campbell
1/19/31	3 <sup>RD</sup> INSP MASONITE WALLS Columns & others A.H. Campbell
2/3/31	4 <sup>TH</sup> INSP Alterations Completed OK A.H. Campbell
2/3/31	COMPLETED AND O.K. <i>Alfred H. Campbell</i> INSPECTOR