

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-6084</i>	LOCATION <i>3076 - 65th St</i>
DATE <i>7/31/40</i>	PURPOSE <i>Erect new double garage</i>
ZONE <i>—</i>	OWNER <i>J. Hanson</i>
	ARCHT. <i>—</i>
	CONTR. <i>—</i>

VAL <i>2500⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>4</i>	APTS.	SIZE
------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>—</i>
VENT SHAFTS		BOILER ROOMS	<i>700⁰⁰</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
8-2-40	18 Prop Forming of Piers
7-28-40	2 " Forming " Piers
"off" 6	Finished of Piers
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>