

② 21145-8

| | | | | | |
|--|---------|-------------------------------------|-------|---------------------|---------------|
| Portn. of BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$55.00 | | | | | |
| S.W. $\frac{1}{4}$ of N.W. $\frac{1}{4}$ Sect. 7 T7N R5E | | TYPE BUILDINGS | | R222 F500 file | |
| PERMIT NO. | | | | | |
| F-6513 | | LOCATION 7724 - 24th Street | | A-5 | |
| DATE | | PURPOSE Const. new meeting hall | | | |
| Feb 21-67 | | OWNER St. Anns Catholic Church same | | | |
| ZONE | | ARCH'T Hal Okholm 4728-Oakfield | | | |
| R-1 | | CONT'R Owner same 422-8380 | | | |
| VAL. \$16,000. | | STORIES | ROOMS | APTS. | SIZE |
| | | | | | 2260 sq. ft. |
| INSP. | DATE | BLDG. TYPE V-1 hr. | | OCCUPANCY GROUP B-2 | PHONE (O) (C) |
| FORM | 2-23-67 | Nammors | | | |
| JOIST | | | | | |
| FRAME | 8-21-67 | Nammors | | | |
| SHEET ROCK | 8-21-67 | Nammors | | | |
| FINAL | 8-15-67 | E. Stenlund | | | |



RECORD OF INSPECTIONS MADE BY THE INSPECTOR

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|---|
| 9-17-54 | Pl. 1/2" blue concrete finish. Placed wall and rail at Chapman |
| 9-21-54 | Pl. 1/2" blue concrete finish. Placed wall and rail at Chapman |
| 9-24-54 | Pl. 1/2" blue concrete finish. Placed wall and rail at Chapman |
| 9-23-54 | Pl. 1/2" blue concrete finish. Placed wall and rail at Chapman |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

COMPLETE
AND OK

INSPECTOR

