

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-127864</i>	LOCATION <i>916-30<sup>th</sup> St.</i>
DATE <i>10/12/44</i>	PURPOSE <i>Remod of addy. over permit # B-12715</i>
ZONE	OWNER <i>S. Pallotta</i>
	ARCH'T.
	CON'TR. <i>Owner</i>

VAL.	STORIES	ROOMS	APTS.	SIZE
<i>500.00</i>				
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
10/6/44	3 <sup>RD</sup> /NSP. EXT LATH FOR STUCCO PLASTERING OVER RUSTIC EXTERIOR OF BLDG. <sup>OK</sup> A W Campbell
11/6/44	2 <sup>ND</sup> /NSP. Frame for Rem Bldg moved to rear of lot O. K. <sup>OK</sup> A W Campbell
11/9/44	3 <sup>RD</sup> /NSP. INT. LATH (ROCK LATH) <sup>OK</sup> A W Campbell
12/13/44	4 <sup>TH</sup> /NSP. Bldg Completed <sup>OK</sup> A W Campbell
12/13/44	COMPLETE AND O. K. Alder W Campbell

INSPECTOR