

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA	FINAL INSPECTIONS	
		23 Lochmoor Circle					A-5		
LEGAL DESCRIPTION			OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE	
Lot 347 Southgate Meadows #5							Fuller	9/23/66	
TITLE AND NAME		V/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		
GEN. CONTR. Besco			2777 Alvarado St., San Leandro				ELECTRICAL BY		
ELEC. CONTR.							DATE		
PLBG. CONTR.							PLUMBING BY		
MECH. CONTR.							DATE		
ARCH. ENGR.							MECHANICAL BY		
OWNER Valbrook, Inc.			Same				CERTIFICATE OF OCCUPANCY		
CONST. LOAN LENDER							ISSUED BY		
							DATE		
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
						1177 (449 gar)			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED	

NATURE OF WORK:- Const. dwlg. & att. gar. Plan 503 IC

PERMIT NO. S.P. -	F-3297	MICROFILM RECORD		
ISSUED BY				
ISSUANCE DATE	3/1/66	PLANS AND APPLICATION	REEL NO. 162	FRAME NO:- 145 TO 150
VALUATION	\$ 11,900.00	INSPECTION RECORD	REEL NO. 188	FRAME NO:- 137 TO
R.U.F. FEE	\$	JOB FILE	REEL NO.	FRAME NO:- TO
S.M.I. FEE	\$	R 936 P004 (SOMA)		
PLAN CK. FEE	\$			
SEWER INCL. FEE	\$			
PERMIT FEE	\$ 43.00	REMARKS AND/OR VARIANCES		
	\$			
	\$			
TOTAL FEES	\$			

