

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-13120</i>	LOCATION <i>2308 - Oct.</i>
DATE <i>1/11/45</i>	PURPOSE <i>General repairs to dwg.</i>
ZONE	OWNER <i>A. C. Turpin</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. *1500⁰⁰*

STORIES

ROOMS

APTS.

SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

. DATE .	CONDITION OF WORK-REMARKS
1/18/45	1 ST /HSP. Pipes bet Outside & Ceiling Walls F.R.S. Repair of dry rot & 1 ST F. on Truss with new ones O. K. A. W. Campbell
2/10/45	2 ND /HSP. Frame for Ventilation 2 AP'S 3 RD /HSP. Int. Lat. for 4 TH AP'S O. K. A. W. Campbell
5/23/45	2 ND /HSP. Frame for Lower AP'S. OK A. W. Campbell
5/23/45	3 RD /HSP. EXT. LAT. OK
	COMPLETE AND O. K. INSPECTOR