

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-5964</i>	LOCATION <i>2590-17<sup>th</sup> St</i>
DATE <i>7/12/40</i>	PURPOSE <i>Re construct Roof</i>
ZONE	OWNER <i>Frank Gonzalez</i>
	ARCH'T.
	CONTR. <i>O. case</i>

VAL. <i>3500</i>	STORIES	ROOMS	APTS.	SIZE
------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	



1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

DATE	CONDITION OF WORK-REMARKS
7/12/40	1 <sup>ST</sup> NSP. Frames for Address <sup>OK</sup> <del>OK</del> Add Campbell
8/7/40	2 <sup>ND</sup> NSP. Frames in place
8/21/40	3 <sup>RD</sup> NSP. Ext. Lat. <sup>OK</sup> Add Campbell

COMPLETE AND O. K.

INSPECTOR

