

A997378-379

## BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$16.00

TYPE BUILDINGS

B100 7306 Siller

PERMIT NO. <b>E-1188</b>	LOCATION <b>912 - K Street</b>	A-2		
DATE <b>Apr. 30-62</b>	PURPOSE <b>Remodel exterior theatre entrance.</b>			
ZONE <b>C-3</b>	OWNER <b>Siller, Mier, Clauss Jr. &amp; Mux.</b>			
	ARCH'T <b>Dean Unger 2104-Sutterville Rd.</b>			
	CONT'R <b>John F. Otto 4322-24th Street</b>			
VAL. <b>\$3,000.</b>	STORIES	ROOMS	APTS.	SIZE <b>(non structural)</b>
INSP.	DATE	BLDG. TYPE <b>III-1 hr.</b>	OCCUPANCY GROUP <b>F-2</b>	
FORM				
JOIST				
FRAME	<b>7-3-62</b>	<i>Filled</i>		
SHEET ROCK	<b>7-3-62</b>	<i>Filled (Siller)</i>		
FINAL	<b>9-19-62</b>	<i>Re built</i>		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	COMPLETE AND OK
	INSPECTOR