

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-2975.</i>	LOCATION <i>417 - 32nd St.</i>
DATE <i>5/1/39</i>	PURPOSE <i>Repairs to duct due to termite</i>
ZONE	OWNER <i>H. Dempsey</i>
	ARCH'T.
	CON'T'R. <i>W. H. Howard</i>

VAL. <i>2000</i>	STORIES	ROOMS	APTS.	SIZE
------------------	---------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="295 911 438 958">COMPLETE AND O. K.</p> <p data-bbox="1204 927 1348 958">INSPECTOR</p>