

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-7618</i>	LOCATION <i>4856 11 Ave</i>			
DATE <i>12/23/37</i>	PURPOSE <i>Repair Sump</i>			
ZONE	OWNER <i>Matthie Little</i>			
	ARCH'T.			
	CONT'R. <i>Irwin Roofing Co.</i>			
VAL. <i>10400</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS	ELEVATOR SHAFTS			
VENT SHAFTS	BOILER ROOMS			
OWNER'S INSPECTOR	SPRINKLER SYSTEM			
LATH	GAS VENTS			
FIRE ESCAPES	CHIMNEYS			
STAND PIPES	SKYLIGHTS			

DATE	CONDITION OF WORK-REMARKS
	COMPLETE AND O. K.
	INSPECTOR

APPLICATION FOR PERMIT TO BUILD

Street No. 2455 Lot 40 Block 10
 Owner Wm. S. Baker Address 2455 24th St.
 Architect _____ Address _____
 Contractor _____ Address _____

Permit
Date
District

Kind of Building _____

Foundation _____

	Girder		Span		Mud Sills	
	1st Floor	2nd Floor	3rd Floor	4th Floor	5th Floor	6th Floor
Joists						
Span						
Partitions						
Non-bearing Partitions						
Roof Height						
Outside Walls						

Ceiling Joists _____ Span _____
 Roof _____ Rafters _____
 Water Heater _____ Chimney _____

Size of Building—Length _____ Width _____ Height _____

It is hereby agreed that this building will be constructed in conformity with the Ordinances of the City of Sacramento and the Laws of the State of California.

Estimated cost, \$ _____
 Plans must be submitted.

[Signature]
 Owner or Owner's Representative.

