

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>B-14029</b>	LOCATION <b>1011-7th. (Rear)</b>
DATE <b>8/13/40</b>	PURPOSE <b>New roof &amp; Ceiling of Fire</b>
ZONE	OWNER <b>Conrad Licorick</b> <b>Loss</b>
	ARCH'T.
	CONT'R. <b>Owner</b>

VAL. <b>600<sup>00</sup></b>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
8/27/45	2 <sup>ND</sup> INSPECTION. Frame for New Roof to replace
	Red one recently damaged by fire.
	O.K. All Complete
	3 <sup>RD</sup> INSPECTION. Sheetrock & Patching of Plaster
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="323 870 452 911">COMPLETE AND O. K.</span> <span data-bbox="1179 885 1313 911">INSPECTOR</span> </div>