

R252 E247

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS

PERMIT NO. <b>G-2249</b>	LOCATION <b>1617 - 37th Street</b> <b>A-1 (17)</b>
DATE <b>12-31-68</b>	PURPOSE <b>Repair rot damage to shower in dwlg.</b>
ZONE	OWNER <b>J. Erick</b> <b>Same</b>
	ARCH'T
	CONTR <b>Neidhardt Termite 1509-Park Blvd.</b>

VAL. <b>\$600.</b>	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE <b>V</b>	OCCUPANCY GROUP <b>I-1</b>	PHONE (OL) (C) <b>371-9562</b>
FORM				
JOIST				
FRAME SHEET ROCK	<b>1-14-69</b>	<b>Hammers</b>		
FINAL	<b>2-12-69</b>	<b>J. Burdette</b>		



DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	COMPLETE AND OK <span style="float: right;">INSPECTOR</span>

