

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10,316</i>	LOCATION <i>230 - 1 St.</i>
DATE <i>5/2/42</i>	PURPOSE <i>Repairs to interior ston</i>
ZONE	OWNER <i>A. Wong.</i>
	ARCH'T.
	CONT'R. <i>Chas Vanina.</i>

VAL. <i>25000</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
6/30/42	Alterations and Repairs to Corner Store Completed OK A.W. Campbell
7/30/42	COMPLETE AND O. K. <i>Allen W. Campbell</i> INSPECTOR