

R280 F444-470

Ptn. of BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$674.50

North Sacto. Sub. #8
(See Plot Plan)

TYPE BUILDINGS

R308 F52-53 file

PERMIT NO.
G-6687

LOCATION 267E - Rio Linda Blvd. A-7 (66)

DATE
May 5-70

PURPOSE Const. 66-unit Apartment House

OWNER OGO Associates 8512-Whitworth Dr. L.A.

ZONE
R-3

ARCH'T Mel List Sacto.

CONTR J. J. Stevens Const. Same 925-2870

VAL. \$547,800.

STORIES
3

ROOMS

APTS.
66

SIZE

46,110 sq. ft.

INSP.

DATE

BLDG. TYPE V-1 hr.

OCCUPANCY GROUP H-1

PHONE (O) (C)

FORM

5-28-70

OK slab - lowway

JOIST

FRAME

7-15-70

ribs (1st fl. N. side)

SHEET ROCK

7-31-70

substrate (1st fl.)

FINAL

7-29-71

Per Co

Certificate not ENT

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
5-6-70	PK interior parking Callaway
5-8-70	pk north prism Callaway
5-11-70	PK 7th reader Callaway
5-13-70	PK floor parking Callaway
5-14-70	PK bridge structure parking Sullivan
5-14-70	PK slab per Simon & Schuster
5-23-70	PK slab - 1st floor
5-23-70	PK slab - 2nd floor section
5-26-70	PK 7th reader
5-30-70	PK slab Callaway
6-23-70	PK partial frame, etc. to 1st floor
6-29-70	PK 2nd walls
6-29-70	PK wall & bay rail - 1st floor Callaway
6-30-70	PK wall & bay rail Sullivan
7-3-70	PK ramp for bay rail Kelle
7-7-70	COMPLETE PK ramp Kelle
7-9-70	AND ON PK 1st bay with partial frame INSPECTOR

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

Card #2

PERMIT NO. G-6687	LOCATION 2671 - Rio Linda Blvd. A-7 (66)
DATE May 5-70	PURPOSE Const. 66-unit apartment house
ZONE 2-3	OWNER OGO Assoc. 8512-Whitworth Dr. L.A.
	ARCH'T Mel List
	CONTR J. J. Stevens Const. Same 925-2870

VAL. \$547,800.	STORIES 3	ROOMS	APTS. 66	SIZE 46,110 sq. ft.
-----------------	--------------	-------	-------------	------------------------

INSP.	DATE	BLDG. TYPE V 1 hr.	OCCUPANCY GROUP H-1	PHONE (O) (C)
-------	------	-----------------------	------------------------	---------------

FORM		
JOIST		
FRAME		
SHEET ROCK		
FINAL		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
7-10-70	Erected frame - not steady. <i>Kirk</i>
7-14-70	OK frame 1st fl. south side. <i>Kirk</i>
7-20-70	OK frame 2nd floor. <i>Chapin</i>
7-22-70	OK (over) right side (unit). <i>Chapin</i>
7-24-70	OK partial frame. <i>Chapin</i>
7-27-70	OK 2nd floor 10 frame. <i>Kirk</i>
7-30-70	OK 1st fl. <i>Kirk</i>
7-31-70	OK 2nd floor. <i>Kirk</i>
7-1-70	Before final clear with engineers
7-2-70	Refer to surface drawings
7-2-70	OK 1st fl. but raise columns with
	Chapin to see missing temporary wall. <i>Chapin</i>
COMPLETE AND OK	INSPECTOR