

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>A-1597</i>	LOCATION <i>4209 - V Street</i>			
DATE <i>4/30/34</i>	PURPOSE <i>To add living room</i>			
ZONE <i>2-Fam.</i>	OWNER <i>side of dwelt. Mrs. Mason</i>			
ARCH'T	CONT'R <i>John Bond</i>			
VAL. <i>130<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
Light Shafts	Elevator Shafts			
Vent Shafts	Boiler Rooms			
Owner's Inspector	Sprinkler System			
Lath	Gas Vents			
Fire Escapes	Chimneys			
Stand Pipes	Skylights			

DATE	CONDITION OF WORK-REMARKS
4/30/32	Made Partial Frame work for
	Juniata rd. bed rock on west side of bank. 4' below ground surface.
	2 <sup>nd</sup> NSP. Balance of 4' from top of bed rock.
5/10/32	4 <sup>th</sup> NSP. Attrition - on bed rock.
5/10/32	COMPLETE AND O. K. <i>Alvin M. [Signature]</i> INSPECTOR