

K 239 F 99

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$5.00

**TYPE BUILDINGS**

<b>PERMIT NO.</b>			
G-531	LOCATION 2500-02 - Portola Way A-2 (25)		
<b>DATE</b>	PURPOSE Repair pest damages on dwelling & garage		
June-3-68	OWNER Katherine Cunningham Same		
<b>ZONE</b>	ARCH'T 446-7821		
R-1	CONTR Orchard Supply Co. 1731 - 17th Street		

VAL. \$400.	STORIES	ROOMS	APTS.	SIZE
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
<b>FORM</b>	6-6-68	Summers		
<b>JOIST</b>				
<b>FRAME</b>				
<b>SHEET ROCK</b>				
<b>FINAL</b>	7-10-68	Fuller		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
4-10-69	OK from Dept & was used Callaway
	COMPLETE AND OK <span style="float: right;">INSPECTOR</span>