

ISSUED

SEP 20 1929 BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

SACRAMENTO TYPE VII BUILDINGS

BUILDING NO. 3177 LOCATION 2<sup>nd</sup> STORY BRICK BLDG. 1515-18<sup>TH</sup> ST.

DATE Sept 20, 1929 PURPOSE Re-roof over old roof with Combination Roof ROOMS APTS. PHONE

OWNER MEETING CANDY FACTORY ARCH'T

ZONE Multiple-Family CONT'R OAK PARK ROOFING CO.

VAL. 638<sup>00</sup> STORIES 2 SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
EX WALL	Joints						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	



DATE	CONDITION OF WORK—REMARKS
	COMPLETED AND O.K. <span style="float: right;">INSPECTOR</span>

