

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-14001</i>	LOCATION <i>1016 - 10<sup>th</sup> St.</i>			
DATE <i>5/7/45</i>	PURPOSE <i>Repairs to interior of Bldg.</i>			
ZONE	OWNER <i>Herman Davis</i>			
	ARCH'T.			
	CONTR. <i>A. J. Fisher</i>			
VAL. <i>208<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

..DATE.	CONDITION OF WORK--REMARKS
5/8/45	2 <sup>ND</sup> / NSP. Frame for Interior Alterations & Repairs to Store formerly occupied by China Clipper Restaurant
	Veneer Wall Panels replaced with 3/8" Rock Lath & Plaster. LATH. <sup>OK</sup>
	R.W. Campbell
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>