

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. B-9843	LOCATION 2628 - G. St
DATE 1/20/42	PURPOSE Gen. Repairs dwl.
ZONE	OWNER G. Rushing estate
	ARCH'T.
	CONTR. J. A. Payne

-VAL 116 ⁰⁰	STORIES 1	ROOMS	APTS.	SIZE
----------------------------------	---------------------	--------------	--------------	-------------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
2/14/42	Repairs to red dowsy Completed. Advised Contractor to provide either metal or asbestos on ceiling of rear room, above fireplace to smoke pipe from stove to avoid blistering of wood ceiling by heat from stove.
2/16/42	COMPLETE AND O. K. <i>Allen W Campbell</i> INSPECTOR