

## BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD


## TYPE BUILDINGS

PERMIT NO. <i>B-10,483-</i>	LOCATION <i>2214 - E St.</i>
DATE <i>6/23/42</i>	PURPOSE <i>Repairs to porch rear dwlg</i>
ZONE	OWNER <i>Tom - Angello</i>
	ARCH'T.
	CONT'R. <i>Owner</i>

VAL. <i>280<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

OK

DATE	1 <sup>ST</sup> /NSP PIER'S CONDITION OF WORK-REMARKS
6/24/42	2 <sup>ND</sup> /NSP. Frame for enlarging rear room
	7 Dwg. O.K. A.W. Campbell
6/24/42	3 <sup>RD</sup> /NSP. INT WALLS & CEILING TO BE KNOTTY-PINE
7/17/42	4 <sup>TH</sup> /NSP. A. C. C.
	COMPLETE AND O. K. 
	INSPECTOR