

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <b>A-717</b>	LOCATION <b>631-71st St.</b>
DATE <b>June-26-33</b>	PURPOSE <b>1st. 1-7 room. 4 bath etc. with porch</b>
ZONE <b>Gen. Com</b>	OWNER <b>John J. ... Lesse.</b>
	ARCH'T
	CONT-R
	PHONES

VAL. <b>5000</b>	STORIES	ROOMS	APTS.	SIZE
------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
7/7/33	1 <sup>ST</sup> N.S.P. Footings in Place for Recovery
	Building at Service Station. <sup>OK</sup> H.H. Campbell
7/25/33	2 <sup>ND</sup> N.S.P. (PARTIAL) Frame in place. <sup>OK</sup> H.H. Campbell
10/20/33	2 <sup>ND</sup> N.S.P. Balance frame in Place. <sup>OK</sup> H.H. Campbell
10/31/33	4 <sup>TH</sup> N.S.P. Accessory Bldg. Complete. <sup>OK</sup> H.H. Campbell
10/31/33	COMPLETE AND O. K. <i>Walter J. Campbell</i> INSPECTOR