

1162 7435

## BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

## TYPE BUILDINGS

PERMIT NO. E-9806	LOCATION 2600 - W Street				A-2
DATE Mar 4-65	PURPOSE Repair termite damage to dwelling				
ZONE	OWNER Willie Lum 2600 - U Street				
	ARCH'T /GIB-1882				
	CONT'R Valley Termite Co. 1617-18th Street				
VAL \$800.	STORIES	ROOMS	APTS.	SIZE	
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	3-10-65	Plaster			
JOIST					
FRAME	3-24-65	Plaster			
SHEET ROCK					
FINAL	3-31-65	E. Lawen		ENT	

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
3-18-65	FORM - FORM P.T. NOT WORK - E. K. ...
3-22-65	Flashing required at back steps - Form wood on concrete of rear stairs - Bolt missing in window frame
3-23-65	P.T. BACK STEPS FORMS NOT COMPLETE - STUDS NOT Nailed - 4x4 posts on dirt & ...
3-24-65	Several items Not complete Blueprints
COMPLETE AND OK	INSPECTOR