

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>B-8631</b>	LOCATION <b>4840 - East</b>
DATE <b>7/8/41</b>	PURPOSE <b>Erect new dwg. for</b>
ZONE	OWNER <b>L. Loddick.</b>
	ARCH'T.
	CONTR. <b>John Loddick.</b>

VAL. <b>5800</b>	STORIES <b>2</b>	ROOMS	APTS.	SIZE
------------------	------------------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<b>Area</b>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<b>1600 sq ft</b>
LATH	GAS VENTS	<b>@ 394</b>
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
7/21-41	1 <sup>st</sup> Ins p Form on Punter
8/19-41	2 <sup>nd</sup> Ins p Form on Punter
9-2-41	3 " Lath last Punter
11/3-41	4 " Formed of 9th Punter
	<p data-bbox="264 865 393 906">COMPLETE AND O. K.</p> <p data-bbox="1127 880 1268 906">INSPECTOR</p>