

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-454</i>	LOCATION <i>1708 - E. Ryan</i>			
DATE <i>4/28/38</i>	PURPOSE <i>Repairs to dwg & foundation</i>			
ZONE <i>res com</i>	OWNER <i>J. Joncetti</i>			
	ARCH'T. <i>Owner</i>			
	CON'TR. <i>Owner</i>			
VAL. <i>5803</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
5/1/38	1 st / NSP. Frame for Duly moved in on rear of lot. O.K. <i>McCampbell</i>
6/27/38	2 nd / NSP. Frame. Owner agreed to take out Additional Permit for adding 6 ft to Duly
" "	and Permitted. Duly with <i>Dapless</i> <i>McCampbell</i>
7/12/38	Owner took out Additional Permit. ^{OK} <i>McCampbell</i>
7/21/38	3 rd / NSP. Int Lot inc. <i>Patton</i> ^{OK} <i>McCampbell</i>
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>