

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-1357</i>	LOCATION <i>3349 - Ferris Way</i>
DATE <i>6/29/40</i>	PURPOSE <i>Repair of deck wood</i>
ZONE	OWNER <i>B. M. Peterson</i>
	ARCH'T.
	CONTR. <i>H. J. Weidman</i>

VAL. <i>1400=</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

DATE	CONDITION OF WORK-REMARKS
7/2/45	Re Strengthening of Roof of Dry Comp. Ltr.
7/2/45	COMPLETE AND O. K. <i>Walter D. Campbell</i> INSPECTOR