

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>1812-A.</i>	LOCATION <i>2210 - 10<sup>th</sup> O Street</i>		
DATE <i>7/9/34</i>	PURPOSE <i>To exist small <sup>Building</sup> PHONES Used for Sales Rooms</i>		
ZONE <i>Lim. Retail</i>	OWNER <i>Owner</i>	ARCH'T	
	CONT'R <i>Frank Williams</i>		
VAL. <i>97500</i>	STORIES	ROOMS	APTS.
			SIZE
Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
7/10/34	1 <sup>ST</sup> WSP. Frame for 1-Story Repair Shop Bldg. Concrete floor to be cast with foundation. <sup>OK</sup> A.W. Campbell
7/30/34	2 <sup>ND</sup> WSP. Frame in place <sup>OK</sup> A.W. Campbell
7/31/34	3 <sup>RD</sup> WSP. - No Lathwork or Plasterwork.
7/31/34	4 <sup>TH</sup> WSP. 1-Story Frame Rustic Repair Shop Completed including driveway stripso. <sup>OK</sup> A.W. Campbell
7/31/34	COMPLETE AND O.K. <i>Allen H. Campbell</i> INSPECTOR