

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-3519</i>	LOCATION <i>1117 - G05</i>
DATE <i>7/27/39</i>	PURPOSE <i>Remodel on apart. prop. bldg.</i>
ZONE <i>Gen Com</i>	OWNER <i>Ada Kurth</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>2000</i>	STORIES <i>2</i>	ROOMS	APTS.	SIZE
------------------	------------------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

OLD PEERLESS ORCHARDY BRIDGE

DATE	Re-Inst. Cond. - EYR Work CONDITION OF WORK - REMARKS
8/18/39	2 ND / NSP Frame in one Apt in front end of 2 nd story OK Rd. Complete
	Note Owner will have the Hallway
	Paved in Additional Apts later. A.M.C.
	<p>COMPLETE AND O. K. INSPECTOR</p>