

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
8703 Fallbrook Way		1		FINAL INSPECTIONS	
LEGAL DESCRIPTION					
Lot #270 - Glenbrook #3					
TITLE AND NAME		ADDRESS			
Besco		2777 Alvarado St. San Leandro			
GEN. CONTR.		ZIP			
ELRC. CONTR.		CITY LIC. NO.			
PLBG. CONTR.		TEL. NO.			
MECH. CONTR.		ELECTRICAL BY			
ARCH. ENGR.		DATE			
OWNER		BUILDING BY			
Brookvale Inc.		Calloway			
CONST. LOAN LENDER		DATE			
BLDG. WIDTH		ELECTRICAL BY			
BLDG. LENGTH		DATE			
TOTAL HEIGHT		PLUMBING BY			
NO. OF STORES		DATE			
ROOF CONSTR.		MECHANICAL BY			
AREA 1st FLOOR		DATE			
TOTAL AREA		CERTIFICATE OF OCCUPANCY			
C.S.D.		ISSUED BY			
C.I. CASE		DATE			
REAR YARDS		TOTAL AREA			
SET BACK REQ.		1327 sq. ft.			
USE ZONE		EXISTING BLDG'S SAME LOT			
R-1		HOW USED			
PARK'G REQ.		SPACES			
TREES RMVD.		EXISTING BLDG'S SAME LOT			
SIDE YARDS		CENSUS TRCT. NO.			
NATURE OF WORK:-		Const. Dwlg. & Gar Plan 402-B			

ISSUED BY		MICROFILM RECORD	
ISSUANCE DATE		7/7/66	
VALUATION		\$ 13,100.	
R.D.F. FEE		\$	
S.M.I. FEE		\$	
PLAN CK. FEE		\$	
SEWER INCL. FEE		\$	
PERMIT FEE		\$ 49.00	
TOTAL FEES		\$ 49.00	

PERMIT NO. S.P. - F-4734	
REEL NO. 180	FRAME NO. 491
REEL NO. 199	FRAME NO. 8
REMARKS AND/OR VARIANCES	
JOB FILE REEL NO. 180 FRAME NO. 491 TO 501 REEL NO. 199 FRAME NO. 8 TO 422 TO COMM.	