

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-11546</i>	LOCATION <i>2508 - Portola Way</i>
DATE <i>9/13/43</i>	PURPOSE <i>Repairs to roof comp</i>
ZONE	OWNER
	ARCH'T.
	CONTR. <i>G. J. Johnson</i>

VAL. <i>181⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE.	CONDITION OF WORK—REMARKS
	<p data-bbox="299 926 447 969">COMPLETE AND O. K.</p> <p data-bbox="1268 947 1422 969">INSPECTOR</p>