

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <b>5380</b>	LOCATION <b>79 W. 12th St. Hillman Bldg. 29-23-24-26</b>		
DATE <b>10/17/59</b>	PURPOSE <b>Food Res. Garage</b>	ROOMS <b>8</b>	APTS. <b>7</b>
ZONE	OWNER <b>B. W. Marsh</b>	PHONE	
	ARCH'T <b>J. H. Lund</b>		
	CONT'R <b>J. H. Lund 3300 Center Way</b>		
	VAL. <b>9</b>	STORIES <b>2</b>	SIZE <b>111 x 111 6'</b>

FOUNDATION	STORY	BSMT	1	2	3	ROOF			Cement Tests
EX WALL	Jolts						Chimneys		
	Beams and Girders						Fire Place		
Int Wall	Studs and Columns						Gas Water Heater		
	Bridging Fire Stops						Heater Closet		
Piers	Fire Escape Stand Pipes						Furnace		Window Courts
	Metal Lath						Boiler Room		
	Stairs						Elevator Shaft		



DATE	CONDITION OF WORK—REMARKS
10/21/29	1 <sup>st</sup> Insp Forms in place + OK P.H. Renter
10/29/29	2 Insp Forms a " " P.H. Renter
11/5/29	3 Insp Ext + Int work on P.H. Renter
10/19/29	4 Insp Inspected + OK P.H. Renter
	Street cleaned up + Certificate of Occupancy Issued.
	COMPLETED AND O.K. <i>P.H. Renter</i> INSPECTOR