

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-567</i>	LOCATION <i>Make general repairs 3173-35th St.</i>	PURPOSE <i>Swelling</i>	OWNER <i>Albert Givan</i>	PHONES
DATE <i>May 8-33</i>	ARCH'T <i>Owner</i>	CONT-R <i>Install 1 Bag of Arlic's Shoring to Same with Downer Under</i>		
ZONE <i>2-Fam.</i>	VAL. <i>400 00</i>	STORIES <i>1</i>	ROOMS	APTS.
				SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
5/17/33	<p>2ND / NSP. Frame for Installing 1 Bed Room + Storage Room in R.R.C. with Stairway to same and new double windows cut in rear of roof for same.</p> <p>O.K. <i>Phil Campbell</i></p>
	<p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>