

*AR 67 113-216*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

\$16.00

**TYPE BUILDINGS**

<b>PERMIT NO.</b> E-4495	<b>LOCATION</b> 5851-55th Street	A-1
<b>DATE</b> Jul. 22, 63	<b>PURPOSE</b> Const. 3 room add to rear & side exist dwe!	
<b>ZONE</b> R-1	<b>OWNER</b> L. J. Altop.	
	<b>ARCH'T</b>	
	<b>CONT'R</b> Owner	

<b>VAL.</b> \$2,600	<b>STORIES</b> 1	<b>ROOMS</b> 3	<b>APTS.</b>	<b>SIZE</b> 378 S. F.
---------------------	---------------------	-------------------	--------------	--------------------------

INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)
FORM	<i>8-16-63</i>	<i>Form</i>		
JOIST	<i>9-4-63</i>	<i>Calway</i>		
FRAME	<i>12-3-63</i>	<i>Form</i>		
SHEET ROCK	<i>12-3-63</i>	<i>Form</i>		
	<i>3-26-64</i>	<i>Curt</i>		
FINAL	<i>2/23/65</i>	<i>Proc</i>		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
1-15-63	PTA Testing not deep enough <i>Green</i>
1-20-65	Not home SF 2-33-65 <i>Red</i>
COMPLETE AND OK	INSPECTOR

1. The test results shall be reported to the Engineer in writing within 10 days of the completion of the test.