

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>A-2309</b>	LOCATION <b>1106-37<sup>th</sup> St</b>			
DATE <b>11/27/34</b>	PURPOSE <b>Construct 2-Storey Semi-Detached with Porch; Porches over</b>			
ZONE <b>2-Family</b>	OWNER <b>DAVID POLIHSON SAME</b>			
	ARCH'T			
	CONT'R <b>OWNER (DAY-WORK)</b>			
VAL. <b>725<sup>00</sup></b>	STORIES <b>2</b>	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK-REMARKS
11/28/34	1 <sup>ST</sup> WSP. Frame in place. <sup>O.K.</sup> R.W. Campbell
12/17/34	2 <sup>ND</sup> WSP. PARTIAL FRAME <sup>started installation of</sup> about Par. Chimney. R.W. Campbell
12/27/34	2 <sup>ND</sup> WSP. Frame in Apt above Garage <sup>O.K.</sup> R.W. Campbell
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>

