

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>H-7325</i>	LOCATION <i>906 - R. Pt.</i>
DATE <i>10/29/37</i>	PURPOSE <i>Reface front stone</i>
ZONE	OWNER <i>Moss Stores Inc.</i>
	ARCH'T.
	CON'TR. <i>A. Fisher</i>

VAL. <i>750<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
11/5/07	Made inspection of installation Take Panel
	to face of Stone Block above Stairs-
	Windows & Transoms have been checked &
	face of Wall ok All Complete
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="303 871 432 912">COMPLETE AND O. K.</span> <span data-bbox="1177 888 1316 912">INSPECTOR</span> </div>