

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | | | | | |
|-----------------------------|---------|-------------------------------------|------------------|------|--|
| PERMIT NO. <i>B-2022</i> | | LOCATION <i>414. 24th street</i> | | | |
| DATE <i>4-22-50</i> | | PURPOSE <i>Repair porch to deck</i> | | | |
| ZONE | | OWNER <i>D. L. Litch</i> | | | |
| | | ARCH'T. | | | |
| | | CONTR. <i>Clune</i> | | | |
| VAL. <i>\$100</i> | STORIES | ROOMS | APTS. | SIZE | |
| LIGHT SHAFTS | | | ELEVATOR SHAFTS | | |
| VENT SHAFTS | | | BOILER ROOMS | | |
| OWNER'S INSPECTOR | | | SPRINKLER SYSTEM | | |
| LATH | | | GAS VENTS | | |
| FIRE ESCAPES | | | CHIMNEYS | | |
| STAND PIPES | | | SKYLIGHTS | | |

| DATE | CONDITION OF WORK-REMARKS |
|---------|-----------------------------|
| 5/25/50 | Frame Insp. <i>ET Jones</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

COMPLETE
AND O. K.

INSPECTOR