

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>A-6735</b>	LOCATION <b>FORUM BLDG - 906 K ST.</b>
DATE <b>Aug 2nd 1937</b>	PURPOSE <b>Remodel Store Front &amp; Interior of Store</b>
ZONE <b>Gen. Com.</b>	OWNER <b>MOSS STORES, INC. (LESSEE)</b>
	ARCH'T.
	CONTR. <b>MULLEN MFG. Co 60-80 Rausch St. S.F.</b>

VAL. <b>3000<sup>02</sup></b>	STORIES	ROOMS	APTS.	SIZE
-------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
8/5/37	2 <sup>ND</sup> FLOOR. Frame for installing Studing on each side with 3/8" Ceiling Joists below 2 <sup>ND</sup> Floor Reinf Conc Floor Slab. in Store  O.K. A.W. Campbell
8/13/37	3 <sup>RD</sup> FLOOR. INT. LATH O.K. A.W. Campbell
8/20/37	4 <sup>TH</sup> FLOOR Remodeling of Store Complete A.W. Campbell
8/20/37	COMPLETE AND O. K. <i>Alden J. Campbell</i> INSPECTOR