

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
11/5/29	B. \$ 20.00	5503	Addn to privite garage	Termuligro	Owner		
12/7/76	E. \$ 200.00	D-9634 \$ 20.00	Install new service	Mr. Hawratti	Pioneer Electric	Charles	12-17-76
12/17/76	B. \$ 300.00	D-9878 ⁶⁻⁸⁶²⁷ \$ 20.00	Reeroof-Dwlg	Same	P.O. Box 289 W. Vacaville	Riolo	5/5/77B
1/4/77	M.P. E 200.00	E-0009 \$ 20.00	Relocate W/H & change out kit sink. Dwlg	Thomas Harlty	Owner	DiLoreto	
1/25/77	B. \$ 500.00	E-581 \$ 20.00	New flooring in back porch and flur floor joist porch is 7x12 Dwelling	Thomas Hanratty	Owner	Riolo	2/19/77B
5/3/77	B. \$ 460.00	E-3088 \$ 20.00	Termite repair -Remove and replace beetle and subterrance damage joist mud sill and flooring-Dwlg	Mr. Henretty	Lee's Termite	Riolo	5/23/77B

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
5503	R465F306 -Lowly	D-9878	R483F622		
D-9634	R465F306	E-3088	R482F598		
D-9634	R467F118 final				
D-9878	R466 F474				
E-0009	R468 F165				
E-0009	R470 F605 Final				
E-581	R472F189				
E-3088	R481F025				
E-581	R473F193 final				

