

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>B-10,908</b>	LOCATION <b>3341 - 42 St.</b>
DATE <b>11/18/42</b>	PURPOSE <b>Repairs to dwly. due to termite</b>
ZONE	OWNER <b>L. White.</b>
	ARCH'T.
	CONTR. <b>R. L. Spray Moore</b>

VAL.	STORIES	ROOMS	APTS.	SIZE
<b>375<sup>00</sup></b>				
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

<b>DATE</b>	<b>CONDITION OF WORK—REMARKS</b>
<b>COMPLETE AND O. K.</b>	<b>INSPECTOR</b>