

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. 4987	LOCATION <i>Roofing</i>	PHONES <i>911-26</i>
DATE	PURPOSE <i>Repair</i>	
OWNER <i>W. Crawford</i>	ARCH'T	
CONTR <i>Dallman Supply</i>		
STORIES <i>190</i>	ROOMS	APTS.
		SIZE

ISSUED
 AUG 26 1929
 SACRAMENTO
 BUILDING DIVISION

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand-pipes			

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="327 854 480 896">COMPLETED AND O. K.</p> <p data-bbox="1121 875 1259 896">INSPECTOR</p>