

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>No Charge</i>	LOCATION <i>1920-21st St.</i>		
DATE <i>May 16, 1930</i>	PURPOSE <i>Reshingle Dormer Roof</i>	ROOMS	APTS.
ZONE <i>2 Family</i>	OWNER <i>A. B. CARTER</i>	PHONE	
	ARCH'T		
	CONTR <i>DAN. TATTI</i>		
	VAL. <i>25⁰⁰</i>	STORIES <i>2</i>	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Jolts						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	



DATE	CONDITION OF WORK—REMARKS
5/16/30	Inspected Re-Shingling of Dormer Roof on front part of Main Roof Completed
	O. K. <i>Aldred Campbell</i>
5/16/30	COMPLETED AND O. K. <i>Aldred Campbell</i> INSPECTOR

