

R271-1351

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$15.00

TYPE BUILDINGS

|                             |   |            |                 |               |
|-----------------------------|---|------------|-----------------|---------------|
| PERMIT NO.<br><b>G-5161</b> | LOCATION <b>2541 - 51st Street A-1 (17)</b>         |            |                 |               |
| DATE<br><b>Nov. 13-69</b>   | PURPOSE <b>Repair pest damage to dwelling</b>       |            |                 |               |
| ZONE<br><b>R-1</b>          | OWNER <b>H. Peters same</b>                         |            |                 |               |
|                             | ARCH'T  |            |                 |               |
|                             | CONT'R <b>Paramont Pest Control 6405-Elvas Ave.</b> |            |                 |               |
| VAL. <b>\$1,500.</b>        | STORIES   | ROOMS      | APTS.           | SIZE          |
| INSP.                       | DATE  | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM                        |   |            |                 |               |
| JOIST                       |   |            |                 |               |
| FRAME SHEET ROCK            | <b>11-18-69 Re-lap (N.W. side)</b>                  |            |                 |               |
| FINAL                       | <b>11-24-69 Pesto</b>                               |            |                 |               |

| <b>DATE</b> | <b>SPECIAL CONDITIONS OF WORK — REMARKS</b> |
|-------------|---|
|             |   |
|             |   |
|             |   |
|             |   |
|             |   |
|             |   |
|             |   |
|             |   |
|             |   |
|             | <b>COMPLETE<br/>AND OK</b>                  |

**INSPECTOR**