

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

|                             |   |
|-----------------------------|---|
| PERMIT NO.<br><i>6490-A</i> | LOCATION<br><i>811 - 44<sup>th</sup> Street</i> |
| DATE<br><i>6/16/37</i>      | PURPOSE<br><i>Re-roof double corrug. sh.</i>    |
| ZONE                        | OWNER<br><i>Sarah Platt</i>                     |
|                             | ARCH'T.   |
|                             | CONTR.<br><i>Roof Rev. Co.</i>                  |

|                   |                  |       |       |      |
|-------------------|------------------|-------|-------|------|
| VAL. <i>14400</i> | STORIES <i>1</i> | ROOMS | APTS. | SIZE |
|-------------------|------------------|-------|-------|------|

|                   |  |                  |  |
|-------------------|--|------------------|--|
| LIGHT SHAFTS      |  | ELEVATOR SHAFTS  |  |
| VENT SHAFTS       |  | BOILER ROOMS     |  |
| OWNER'S INSPECTOR |  | SPRINKLER SYSTEM |  |
| LATH              |  | GAS VENTS        |  |
| FIRE ESCAPES      |  | CHIMNEYS         |  |
| STAND PIPES       |  | SKYLIGHTS        |  |

| <b>DATE</b> | <b>CONDITION OF WORK—REMARKS</b>   |
|-------------|--|
|             |  |
|             |  |
|             |  |
|             |  |
|             |  |
|             |  |
|             |  |
|             |  |
|             |  |
|             | <p data-bbox="310 976 461 1022"><b>COMPLETE<br/>AND O. K.</b></p> <p data-bbox="1276 996 1427 1022"><b>INSPECTOR</b></p> |